09/522,085 Art Unit 3624 9137.00

Please add the following claims:

- 22. Method according to claim 1, wherein, prior to the process of modifying said ATM, said ATM was incapable of receiving user commands for dispensing cash from a wireless telephone.
- 23. Method according to claim 20, wherein, prior to modifying, no ATMs could receive user commands for dispensing cash from a wireless telephone.
- 24. Apparatus according to claim 16, wherein the transceiver is connectable to a system bus of a computer within the SST.
- 25. Apparatus according to claim 24, wherein the transceiver is assigned a telephone number, and the SST displays that telephone number to customers.
- 26. Method according to claim 15, wherein the SST was unable to receive user commands from a wireless telephone prior to the modifying process.
- 27. Method according to claim 7, wherein said ATM was unable to receive signals directly from a wireless telephone prior to the modifying step.